

Dayton Trails Water System ID #02715V													
Location Information		System-Owned Portion				Customer-Owned Portion			Entire Service Line Material Classification (required)	Other Potential Sources of Lead		Lead Service Line Replacement (LSLR)	
Location Identifier (required)		System-Owned Portion Service Line Material Classification (required)	If Non-Lead in Column D, Was Material Ever Previously Lead?	Basis of Material Classification (required)	Notes	Customer-Owned Portion Service Line Material Classification (required)	Basis of Material Classification (required)	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Date of System-owned LSLR	Date of Customer-owned LSLR
Street Address	Other Location Identifier												
Water systems must track addresses of all service lines in their internal inventory. If the system does not use addresses for their location identifier, other options could include a unique ID, parcel number, landmark, intersection, block, or other details to specify service line locations.		Dropdown list includes recommended subclassifications. If "Non-Lead Other", describe in Notes field	Dropdown list. Select Yes, No, or Don't know. Important for determining if downstream/ customer-owned galvanized service line requires replacement	Select option from drop down list. If "Other," describe in the Notes field	Use this field for documenting additional relevant information.	Dropdown list includes recommended subclassifications. If non-lead other, describe in Notes field.	Select option from drop down list.	Use this field for documenting additional relevant information.	Select the proper classification using dropdown list and "Classifying SLs" tab.	For example, lead gooseneck or pigtail where the water main is connected to the service line	Select Yes, No, or Don't Know		
150 W CLOVERDALE		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
360 W DAYTON TRAILS DR		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
61 W BRIDLEWOOD CT		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
211 W DAYTON TRAILS DR		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
190 W DAYTON TRAILS DR		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
196 W DAYTON TRAILS DR		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
670 W DAYTON TRAILS RD		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
150 W PALOMINO PL		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
60 W BRIDLEWOOD CT		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
111 W HEATHERWYND LN		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
198 W DAYTON TRAILS DR		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
30 W SWEETCLOVER CT		Non-Lead plastic	No	Field inspection		Non-Lead plastic	Field inspection		Non-Lead	No	No		
60 W HILLSBOROUGH CT		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
250 W DAYTON TRAILS DR		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
151 W HEATHERWYND LN		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
50 W CROSSWYND CT		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
430 W DAYTON TRAILS DR		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
111 W PALOMINO PL		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
51 W BLUEGRASS CT		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
20 W WESTWYND LN W		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
21 W CROSSWYND CT		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
50 W BLUEGRASS CT		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
51 W CROSSWYND CT		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
50 W COUNTRYSIDE CT		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
210 W DAYTON TRAILS DR		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
850 W DAYTON TRAILS		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
30 W MEADOWS PL		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
20 W BRIDLEWOOD CT		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		
51 W HEATHERWYND LN		Unknown- unlikely lead	No	Statistical method		Unknown- unlikely lead	Statistical method		Unknown	No	No		

[illegible]